



CMT-4 MOISTURE TRANSMITTER

Part No. 21908

-  POWER
-  OK
-  OUTPUT SIGNAL LATCHED

CONNECTIONS

- 1 & 2: SENSOR INPUT
- 3: 4-20mA VDC (-) SIGNAL OUTPUT
- 4: LATCH CIRCUIT INPUT (24VDC +)
- 5: 4-20mA VDC (+) SIGNAL OUTPUT
- 7: GROUND/EARTH
- 9: 24VDC (-) POWER
- 10: 24VDC (+) POWER

TO CHECK CALIBRATION, DISCONNECT SENSOR FROM TERMINALS 1 & 2, PRESS & HOLD BUTTON CALIBRATION OK IF 12.9mA VDC +/- 0.5mA OUTPUT OR 8.7% MOISTURE +/- 0.2% (COTTON SCALE)